INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet,

CERTIFIED CORNER RECORDATION	
Corner S1/16 SEC.S 8/9 T. 29N R.	29W P.M.M. Lincoln County
The new corner monument was established as a resu subdivisional survey was made in accordance with Manual of Surveying Instructions (1973); U.S. Bureau of I	n methods and procedures contained in the
FOUND:	
Found a 1½" iron pipe, S17°W, 3.58 feet from S1/16 corner.	
ESTABLISH:	
Set a 5/8" rebar with standard aluminum cap, marked as shown be	elow, from which:
A 19" pine bears S78°W, 16.05 feet distant, marked "S1/16 S8 B' A 12" Douglas Fir bears S67°E, 32.0 feet distant, marked "S1/16	
Set a 6' "U" post 2.0 feet south of monument.	
T29N R29W S1/16 S8 S9 9958 LS 2007	
19" PINE THE STORY 16.05. 16.05. 12" DOUGLAS FIR SKETCH OF CORNER	CERTIFICATION I,
SKEICH OF CORNER	Employer. 3.R.S. Surveying, Inc.
Office of Clerk and Recorder, County ofThis "corner	я
record" was filed for record ^ 213019 BOOK: CCR CCER'S PAGE was noted on the cross-ind STATE OF MONTANA LINCOLN COUNTY	E: 11232 Pages: 1
book no. TAMMY D. LAUER CLERK AND RECORDER	ir's

TAMMY D. LAUER CLERK AND RECORDER

FEE: \$0.00 BY:

TO: J.R.S. SURVEYING P.O.BOX 1050, LIBBY, MONTANA 59923 Cross Index No. H9 T. 29N R. 29W PMM

TAMMY D. LAUER CLERK AND RECORDER

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

• - Corner this sheet