





(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

This corner was established by survey of Libby Airport.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Set a 2 inch galvanized iron pipe 24 inches in ground, at exact corner point indicated on plat of this designated corner, with brass cap marked, from which:

Libby
Airport
COR 1
1970

A 11 in. Ponderosa Pine bears N. 50° E. - 114 1ks - mkd rm

SJS 2532 S

A 10 in. Ponderosa Pine bears S. 87° E. - 28 1ks - mkd rm

Location, attention and bearing tree signs were posted at the corner.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

Plat attached to reverse side of recordation form for corner no. 1 of survey of Libby Airport.

Surveyor's	Seal
------------	------

I, A. R. TRENKLE
certify that the information shown herein is true and correct.

O.R. Trenkle

.....

Tann R30W

No. I

DIAGRAM OF CORNER:

5 18

Signature of Ground Party Chief

STANLEY J. SKOUSEN

Stanley

ħ ...

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

● = Corner recorded on the sheet

2532 S

Registration Number

Office of Clerk and Recorder, County of Lincoln	
This "corner record" was filed for record on the day of	May 19.70, was noted on the cross-index plat and is
assigned page No. 183, in book No. 1	ELEANOR L. VAUGHN, By: Mas Unterno County Official Deputy
·	Cross Index No. 13 T. 29 R. 30 Mer.

540047'30'E. Sec 12 1/4 Corner Found CERTIFICATE:
I hereby certify that I am a registered surveyor in the state of Montana. I have reviewed the survey shown above and have checked all bearings and distances by photogrammetric methods. I have caused manuments to be set at the positions indicated and certify that they are at the type shown, are marked as shown and are sufficient to enable the survey to be retraced. STANLEY J. SKOUSEN MONTANA REGISTRATION NO. 2532 S snow buy, SECTIONS 7 & 18 OF T29N, R3OW PMM. N750000 - 1 okouser SURVEY OF LIBBY AIRPORT Section Carner Found SECTION 12, T29N, R3IW & Sacr Airport Gentities LOCATED IN 182.04 ACTES Note: Corners I livu 20 on the boundary were sell by lunning off centerline stations on the runway. Basis of bearings is a solar observation on the centerling of the runway mode by the U.S. Army Corps of Engineers. Corners Sel (that Survey) 0
21.30 ten Place +10
brass cap stamped 5 200 200 300 400 500 600 700 400 FEET Section Corner Found 6 4 A 129N, R30H (B) Philogramusical Sec 19 Aic ≥ Va Corner Found Sec. 18