## CERTIFIED LAND CORNER RECORDATION

(REFERENCE FSM 7153.53)

## DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

This corner was established by survey of Libby Airport.

## DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 3/30/70

Set a 2 inch galvanized iron pipe 24 inches in ground, at exact corner point indicated on plat of this designated corner, with brass cap marked, from which:

Libby Airport COR 4

A 10 in. Ponderosa Pine bears S. 46½° W. - 52 lks - mkd rm

1970 SJS 2532 S

A 7 in. Ponderosa Pine bears N.  $83^{10}_{2}$  W. - 43 lks - mkd rm

Location, attention and bearing tree signs were posted at the corner.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

Plat attached to reverse side of recordation form for corner no. 4 of survey of Libby Airport.

our	vey	or	8	Dear

I, A. R. TRENKLE certify that the information shown herein is true and correct.

Signature of Ground Party Chief

Signature of Ground Party Chief

I, STANLEY J. SKOUSEN certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

DIAGRAM OF CORNER:


N. Tagn R30W

No. 4

Corner recorded on the sheet

2532 S

Registration Number



. • • 

. .