

CERTIFIED LAND CORNER RECORDATION  
(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

This corner was established by survey of Libby Airport.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED  
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 3/30/70

Set a 2 inch galvanized iron pipe 24 inches  
in ground, at exact corner point indicated on  
plat of this designated corner, with brass  
cap marked, from which:

Libby  
Airport  
COR 6  
1970  
SJS 2532 S

A 11 in. Douglas fir bears N. 3° E. - 13 lks - mkd rm

A 9 in. Ponderosa Pine bears S. 77° W. - 41 lks - mkd rm

Location, attention and bearing tree signs were posted at the corner.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.  
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

Plat attached to reverse side of recordation form for corner  
No. 6 of survey of Libby Airport.

Surveyor's Seal

I, A. R. TRENKLE  
certify that the information shown herein is true and  
correct.

A. R. Trenkle


Signature of Ground Party Chief

I, STANLEY J. SKOUSEN  
certify that I have carefully performed or reviewed the  
work done on the diagrammed corner as reported on this  
recordation form and approve the same.

Stanley J. Skousen

Signature of Surveyor

DIAGRAM OF CORNER:



◆ = Corner recorded on the sheet

2532 S  
Registration Number

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 6th. day of May 1970, was noted on the cross-index plat and is  
assigned page No. 188, in book No. 1

ELEANOR L. VAUGHN, BY: Mae Watson  
County Official Deputy.

Cross Index No. J-1 T. 29 R. 30 Mer.

