

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner 1/4 Cor. of Secs. 15 & 16 T. 29 N. R. 30 W. P.M.M. Lincoln County

I. 1898 G.L.O. record by Paul S. A. Bickel: Set a stone monument and two bearing trees.

1964 B.L.M. Remonumentation by Gerald F. Pittman et al: "The 1/4 sec. cor. of secs. 15 and 16, monumented with a slate stone, 14 x 10 x 5 ins., loosely set and mkd. 1/4 on the W. face, and witnessed by the original bearing trees: At the corner point; set an iron post, 30 ins. long, 2 1/2 ins. diam., 27 ins. in the ground, with brass cap mkd.

T29N R30W

1/4

S16 | S15

1964

from which

The original bearing trees:

A pine, 9 ins. diam., bears S14 1/2° E, 26 lks. dist., mkd. with an overgrown blaze.
(Record: S13 20° E, 26 lks.)

A larch, 7 ins. diam., bears S30 1/2° W, 23 lks. dist., mkd. with an overgrown blaze.
(Record: S34 35° W, 23 lks.)

Bury the original stone alongside of the iron post."

1985 Certified Corner Recordation by Thomas C. Hill, 5612-S: Established one new bearing tree:

A larch, 12 ins. diam., bears S36° E, 38.3 lks. dist., mkd. 1/4 S15 BT.

Set a guard post with Survey Marker decal attached near the corner.

II. Found an iron pipe, 2 1/2 ins. diam., 8 ins. above the ground with 3 1/4 ins. diam., B.L.M. brass cap marked as shown above, from which

A dead pine, 10 ins. diam., bears S14 1/2° E, 17.2 ft. (26 lks.) dist., healed face.


A larch, 9 ins. diam., bears S34° W, 15.2 ft. (23 lks.) dist., healed face.

A larch, 12 ins. diam., bears S36° E, 25.3 ft. (38.3 lks.) dist., visible scribe.

Galvanized steel guard post with Land Survey Marker, South, 1.3 ft.

III. Painted red bands around the bearing trees.

Magnetic Declination: 20° East



SKETCH OF CORNER

CERTIFICATION

1. Mark A. Pederman

certify the information shown herein is true and correct.

Signature Ground Party Chief

Alvah F. Hughes

1. certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

Alvah F. Hughes
Signature of Surveyor & Seal

Date: 12/11/92 Reg. No. 7322 LS

Employer: U.S. FOREST SERVICE

Office of Clerk and Recorder, County of Lincoln. This "corner

record" was filed for record on 1-4-93


was noted on the cross-index plat and is assigned page No. 5245, in

book No. _____

Coral M. Cummings by D.B.
County Official

Cross Index No. L-13 T. 29 N R. 30 W PMM

Sec. 15



• - corner this sheet