

CERTIFIED LAND CORNER RECORDATION
(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

West $\frac{1}{4}$ cor. Sec. 8, T. 29 N., R. 33 W., MPM
Found original bearing tree S 10° W of corner. Scribing almost entirely gone due to fungus growth. Located on west bank of Lake Creek as described where stream veers to the west.

East $\frac{1}{4}$ cor. of Sec. 8
Found original stone and rock mound as described in notes, approximately 700 feet east of Hyw. 202.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

West $\frac{1}{4}$ cor. Sec. 8
Set $\frac{5}{8}$ " x 30 reinforcing steel with stamped cap (aluminum) Date of work: 10/3/74
N 10° E 26.4 feet.
Blazed & scribed 24" pine N 50° E 43.5 feet ~~###~~ " $\frac{1}{4}$ S 8 BT"

Area is adjacent to old fallen bridge that formerly crossed the stream, and is still readily visible.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)


West $\frac{1}{4}$ cor. Sec. 8 to East $\frac{1}{4}$ cor. Sec. 8 bears S 89° 38' E 5076.4 feet.

Surveyor's Seal

I, John J. Allen
certify that the information shown herein is true and correct.
John J. Allen
Signature of Ground Party Chief

I, John J. Allen
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.
John J. Allen
Signature of Surveyor

DIAGRAM OF CORNER:



= Corner recorded on the sheet

3491 S
Registration Number

Lincoln

Office of Clerk and Recorder, County of.....

This "corner record" was filed for record on the 10th day of October 1974, was noted on the cross-index plat and is assigned page No. 373, in book No. 1 Eleanor L. Vaughn, By: Mae Watson Deputy County Official

Cross Index No..... T. 29 N R. 33 W Mer.