INSTRUCTIONS

Original and for subsequent record used to evaluate the corner position

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

escription of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

Certification must be signed and sealed by itegistered Lai
 Fill in Cross Index & Section Diagram at bottom of sheet.

 $2\frac{1}{2}$ dia., around iron post.

#62-82-5

CERTIFIED CORNER RECORDATION

NE Corner Sec. 28 30N 26W Lincoln _County

- Set an iron post, 30 ins. long 2½ ins. diam., 24 ins. in the ground with BLM Brass Cap marked as shown below, from which: A pine, 7 ins. diam., bears N20.5°E, 34 lks. dist., marked T30N R26W S22 BT. A pine 8 ins. dia., bears S9.75°E, 47 lks. dist. marked T30N R26W S27 BT. A pine 7 ins. dia., bears S34°W, 47 lks. dist. marked T30N R26W S 28 BT. A pine 8 ins. dia., bears N57.5°W, 26 lks dist. marked T30N R26W S21 BT. Buried the original stone alongside and raised a flat mound of stone
- Found an iron post with BLM Brass Cap as described above, found II. four bearing trees. Painted corner and all blazes with red paint.

