

CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

No original record of corner establishment on file.
No evidence of corner found on ground.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 5/6/81

At the center 1/4 corner of Section 4:

Set an aluminum pipe, 30 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap marked as illustrated, for exact corner position.


(CAP ILLUSTRATED ON REVERSE SIDE)

From which:

A Fir, 12 ins. diam., bears N.25°W., 13.0 feet dist., mkd. C 1/4 S4 BT.

A Fir, 10 ins. diam., bears N.55°E., 17.0 feet dist., mkd. C 1/4 S4 BT.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



Surveyor's Seal



I, L.A. Dolezal
certify that the information shown herein is true and correct.


L.A. Dolezal
Signature of Ground Party Chief

I, Melvin D. Lauteren
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Melvin D. Lauteren
Signature of Surveyor

DIAGRAM OF CORNER:

SECTION 4
T30N, R27W, PMM



• = Corner recorded on the sheet
C 1/4 SECTION 4,
T30N, R27W, P.M.M.

4232-S
Registration Number

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 29th day of May, 1981, was noted on the cross-index plat and is assigned page No. 1029, in book No. 1