CERTIFIED LAND CORNER RECORDATION

⁴ Corner_	Sections	21 & 22	T. 30 N	., R. 29 W	., <u>MPM</u>
	Record:	(1964 BLM) Set an iror the ground, with brass	s cap marked:		26" in
		·	T.30N. R.29W. 14 521 522 1964		
	From which		<i>1964</i>		
		A pine 14" diam, bears A pine 14" diam, bears Bury original stone al	s N 77 1/2 ⁰ E, 2 s N 51 ⁰ W, 25 1k ongside of iro	8 lks dist. s dist. n post	
	Found:	(1976) An iron post w/trees as described. A	brass cap as d mound of ston	escribed above a e around pipe.	nd bearing
	See certi	ificate of survey #2	213	for ties to adja	cent corners
		·			
	W 87.		I, James R. V certify that the information correct.	Weatherly	ue and
	with the state of	A	Signature	South Party Chief	
\	77	N 77/2°E W	Gordon E.	Sorenson refully performed or review	wed the
1/1/4	450 1	BRASS CAP	work done on the diag recordation form and	rammed corner as reported	on this
	``		Signa	ture of Surveyor	
¥ 1	1/5	U.S.F.S. ROAD	5-24-76	2345ES Registration I	Number
7	DIAGRA	M OF CORNER		SON & COMPANY	
Office		corder, County of Lacely			
		s filed for record on the 2nd day of	of June 19	16, was noted on the cr	oss-index plat and is
	page No. 46	_	Eleanor L.O	augh Mae War	Tem, Deputy
			Cross Index No. P.	·13 _{T.} 30 N	R. 29 W Mer