## INSTRUCTIONS

- INSTRUCTIONS

  1. Original and/or subsequent record used to evaluate the corner position.

  2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

  3. Description of monument and accessories set to perpetuate the corner position.

  4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

  5. Certification must be signed and sealed by Land Surveyor registered, in the State of Montana.

  6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED (	CORNER	RECORD	ATION
-------------	--------	--------	-------

Corne	NE 1/16 & 18 HES 825	T <sup>30</sup>	N., R.	29 W.,	PMM	Lincoln	County
. <u>191</u>	19 HES 825 record by W. P Stephenson cor. no. 18 of this survey and pla	n: Intersect ace a small s	the point	for the N	NE 1/16 cor	of Sec. 13, winder a slate st	hich I adopt one, 28x15x6
	s., 18 ins. in the ground, mkd. 18 fr the exact cor. point, from which:	HES 825 on th	e NE face	, 1/16 S d	on the N fa	ice, and a cross	, (X) on top
	A cross (X) on a tamarack tree, 1 A cross (X) on a fir tree, 18 ins 1/16 S13 18 HES 825 BT.	16 ins. diam. s. diam., bea	, bears N rs N 36 29	78 <sup>°</sup> 23'E, 5'E, 81 11	58 1ks. di ks. dist.,	st. each blazed and	scribed NE
	Raise a mound of stone 4 ft. base	e, 2 ft. high	, NE of th	ne corner.			
	und a stone, 28x15x6 ins., firmly secores (X) on top, from which:	et in place,	mkd. 18 HE	ES 825 on	the NE fac	e, 1/16 S on th	e N face, and
	A fir, 27 ins. diam., bears N $36^{\circ}$ A larch, 19 ins. diam., bears N $7$	E, 53.5 ft. 78 E, 38.3 ft	(81 lks.) . (58 lks.	dist., mk	d. with 18	E and a X in a a snowblaze and	snow blaze. a healed
I. Pai	inted red bands around the bearing t	crees and att	ached Land	l Survey M	lonument an	d Bearing Tree	signs.
	a 6 ft. galvanized steel guard pos st, 3 ft.	st with Land	Survey Mai	rker and P	roperty Bo	undary decals,	
Mag	netic declination: 20 East						
			-	-/ \\	•, •		
	<b>A.</b>						
	<del> </del>	<del></del>		1		CERTIFICATION	1
				/	J,	eth R. Kern	
	,06/64 <sup>1</sup>	1		/]   '	certify the inform	nation shown herein is to	ue and correct.
	\$7/23. <sup>7</sup>	A		$V \mid \cdot \mid$	<u> </u>	Signature Ground Part	y Chlef
	N18°E	W"	•	<b>'</b>     ,	٠,	h F. Hughes	prosents weether form
	38.377	~ 4		<u>.</u>	y me or under	my direction in comp ' (70-22-10), et seq., M.C.	lianco with the Corf
					Ulm	h7 low	Ken 18
						Signature of Surveyor	Scal HUGILE
				}	11	12 Reg. No. <u>7322</u> S. FOREST SERVI	7
	SKETCH OF COF	RNER		1	Employer:	S. POREST SERVI	- 2 - 3 · · · · · · · · · · · · · · · · · ·
Offic	ee of Clerk and Recorder, County o	of Line	eola	>	This ''cor	Sec.	73//
		" Jan	8 10	02	Tins Cor	1161	
reco	rd" was filed for record on	,	4/17.	<u> </u>			
was	noted on the cross-index plat and	is assigned p	page No.	528	36	, in	<del> </del>
book	: No	Coral	M. Count	7 <i>Umw</i> y Official	ing by	<i>BB</i>	+++
		Cross Index No	NE 1/16	& 14 HES	825 30 N	28W PMM •-C	orner this shee