## CERTIFIED CORNER RECORDATION

Corner SW 1/16 S30 T 30 N. R. 30 W. P.M.M. LINCOLN County

- I. Record: 1893 G.L.O. Original Survey of the Libby Creek Guide Meridian by Daniel P. Mumbrue

  1904 G.L.O. Fractional Subdivision by George W. Fessenden and Ranny G. Lyman

  2000 Plat of Swede Mountain Lookout Estates No. 6325, by Alvah F. Hughes, MT Reg. No. 7322LS: Set 5/8 inch diameter rebar with a plastic cap stamped HUGES 7322-LS
- II. Found a 5/8 in. diam. rebar with a red plastic cap marked HUGHES 7322LS
- III. Accepted the position of the found rebar and replaced the red plastic cap with a 3 1/4 in. diam. aluminum cap marked as shown, from which:

The new bearing trees

A fir, 5 ins. diam., bears N65°E, 31.8 ft. dist., marked "X" BT. A fir, 6 ins. diam., bears S23°W, 9.8 ft. dist., marked SW 1/16 S30 BT.

Attached Bearing Tree and Land Survey Monument signs to the bearing trees. Painted red the scribed face and a red band around the bearing trees. Set a 6 ft. galvanized steel guard post 3 ft. South and West of the corner, with Land Survey Monument and Property Boundary decals attached.

T30N R30W S30 X SW 1/16 9750LS 2006


· corner this sheet

Date of Fieldwork: 5/24/2006

Survey crew: Tom Hommel, Steve Boyer Magnetic declination: 20° East assumed

Equipment used: Hand compass and loggers tape

U.S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT 59923 (406) 293-6211



\_<sub>J.</sub> <u>30</u>N. <sub>R.</sub> 30W.

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

Cross Index No.

U-2