

CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

T30N R30W Montana Principal Meridian G.L.O. notebook 3420 page 13
has a 6" cedar tree as the meander corner and 2 bearing trees.
Found a stump hole and the remains of the tree beside it with the scribe
"S15". There were 2 new bearing trees with forest service tags designating
them as bearing trees. There was also one of the original bearing trees.
1) 10" cedar bearing west, 21 lks., marked T30N R30WS15 MC BT
2) 11" cedar bearing S30 E, 65 lks., marked T30N R30W ~~##~~ S14 ~~##~~ MC BT

Record: 4" birch bearing S58 E, 7(8) lks., marked T30N R30WS14 MC BT
Found: bearing tree alive and 13" in diameter with covered scribe

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


Date of work: May '74

No added monumentation

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See sketch on reverse side

Surveyor's Seal



James R. Staples

I, _____
certify that the information shown herein is true and
correct.

James R. Staples

Signature of Ground Party Chief

JOHN C. ERICKSON

I, _____
certify that I have carefully performed or reviewed the
work done on the diagrammed corner as reported on this
recordation form and approve the same.


John C. Erickson

Signature of Surveyor

3979 S
Registration Number

DIAGRAM OF CORNER:

N. T30N R30W



= Corner recorded on the sheet

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 28 day of Mar 1989, was noted on the cross-index plat and is
assigned page No. 3987, in book No. _____

James R. Staples
County Official



10" CEDAR
MRKD. T30N R30W S15 MC BT

15

WEST
21 LKS.



STUMP HOLE & REMAINS ORIGINAL MEANDER
CORNER TREE

S30°E
9 LKS.

14



13" BIRCH WITH OVERGROWN BLAZE

S55°E
63 LKS.



11" CEDAR.
MRKD T30N R30W S14 MC BT

N