CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)
T30N R30W Montana Principal Meridian G.L.O. notes book 3420 page 2 has original stone 20x10x8 15" in the ground marked ½ on the north face with 2 bearing trees. Found no indication of the stone or the bearing trees.
Reset the orner by single proportion method.

Reset the corner by single proportion method.

Corner is on steep northern slope in heavy timber, mostly larch and

fir. Rocky with a whoop of downfall.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: May 74

Set Corps of Engineers brass cap (sketch on reverse side)

- 1) 7" fir bearing N21°W, 20 lks., marked $\frac{1}{4}$ S13 BT
- 2) 10" tamarack bearing S69°W 32 lks., marked \(\frac{1}{4} \) S24 BT

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See reverse side


		DATE OF SOUTH
Surveyor's Seal	I, James R. Staples certify that the information shown herein is true and correct.	DIAGRAM OF CORNER: T30N R30W N.
JOHN C. ERICKSON 3979 S **COISTERED OF THE SURVEY OF THE	Signature of Ground Party Chief JOHN C. ERICKSON certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same. Signature of Surveyor	= Corner recorded on the sheet
	39.795 Registration Number	

Office of Clerk and Recorder, County of Juncohn

This "corner record" was filed for record on the 25 day of Man 1989, was noted on the cross-index plat and is assigned page No. 40/5, in book No.

Form 125-3690

Cross Index No. N 2 3 T 30N R 30W Mer.



10" TAMARACK MRKO 14 SZ4 BT 24

9

. .

·