CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

T30N R30W Montama principal meridian G.L.O. notes book 3416 page 65 has a granite stone 18x10x6 12" in the ground. Found no indication of corner or original trees. Found 4 bearing trees but there was no available recordation. Exhausted all sources of information and found no trace of who or how the trees were set. Reset the corner by double proportion method with $\frac{1}{4}$ 32/33 to the north, $\frac{1}{4}$ 33/4 to the east, $\frac{1}{4}$ 5/4 to the south, and the meander corner 32/5 left bank to the west.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: Thre 14

DIAGRAM OF CORNER:

Set Corps of Engineers brass cap flush to the ground (see sketch on reverse side) and referenced to the 4 existing bearing trees.

- 1) 30" twin fir bearing S49½°W, 150 lks., marked S5 BT
- 2) 24" fir bearing N26°W, 91 1ks., marked S32 BT
- 3) 16" fir bearing N432E, 170 lks., marked S33 BT
- 4) 22" fir bearing S41°E, 287 1ks., marked S4 BT

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See reverse side.....

T3/N R30W Surveyor's Seal MAN NT DO correct ames 32 Signature of Ground Party Chief JOHN C. ERICKSON JOHN C. **ERICKSON** certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this 3979 S recordation form and approve the same. = Corner recorded on the sheet SURVEY PEGISTERED Signature of Surveyor 39795

Office of Clerk and Recorder, County of Sincoln

This "corner record" was filed for record on the 28 day of Mor.

1989, was noted on the cross-index plat and is assigned page No. 4045, in book No.

County Official

Form 125-3690

Cross Index No. A9 T 30 N R 30 W Mer.

Registration Number

