DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

NONE

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

1979 Date of work:.....

Set a 3" X 30" aluminum pipe, 26" above ground, with a collar of stone from which; a 10" ponderosa pine, bears N67°04'W, 66.0 Ft., scribed C\frac{1}{4} S18 BT a 10" douglas fir, bears S11°31'W, 67.0 Ft., scribed C\frac{1}{4} S18 BT a 12" ponderosa pine, bears S79°50'E, 127.4 Ft., scribed C\frac{1}{4}

S18 BT

a 12" douglas fir, bears N37°30'E, 68.2 Ft., scribed $C_{\frac{1}{4}}^{\frac{1}{4}}$ S18 BT

T30 N R30W C 2 S18 5612S 1979

Al. cap marked as shown

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey No. _ 75/

Surveyor's Seal



Gary C. Crismon certify that the information shown herein is true and correct.

ry C Crusus Signature of Ground Party Chief

Thomas C. Hill

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

> 2 Signature of Surveyor

Section 18
Corner recorded on the sheet

N.

DIAGRAM OF CORNER:

C字

T30N R30W

5612-S Registration Number

This "corner record" was filed for record on the 3rd day of March 1980 noted on the cross-index plat and is assigned page No. 660, in book No. County Official Mer.