CERTIFIED CORNER RECORD/

Corner: W 1/4 Sec. 14 Twp. 30N., R.31 W., P.M.M.

Lincoln County Montana

Record: Per BLM records of 1973 Johnnie R. Mendez-Cadastral Surveyor

From the 1/4 sec. cor. of secs. 14 and 15, reestablished by J.W. Ninneman, RLS No. 534, in 1966, determined from ties as shown on plats of subdivisions, and is recorded in the Lincoln County Courthouse. This point has long been recognized as the cor. by adjacent landowners, and is accepted as the best available evidence of the original cor. position.

At the corner point

Set an iron post, 20 ins. long 21/2 ins. diam. 24 ins. in the ground, in a collar of stone, with brass cap mkd.

T 30 N., R. 31 W

1/4

S15 | S 14

1973

From Which:

A Fir, 24 ins. diam. bears S. 191/3° W., 271 1ks. dist., mkd. 1/4 S15 BT.

An X. chiseled on a concrete sidewalk, bears S. 731/2" W., 80 lks. dist.

The NE cor. of a brick church (L.D.S.)., bears S. 57 1/4" W., 348 lks. dist.

Found Evidence:

A 3 1/4 inch BLM Brass Cap marked

T 30 N., R.31W

1/4

S15 | S 14

1973

The NE cor. of a brick church (L.D.S.) bears S 87 1/2" W., 348 lks. dist.

Perpetuation: Established the following two bearing objects: For the West 1/4 of Section 14.

Cross Index No. Twp. 30 N., R. 3 W., P.M.M.

From Which:
A steel fence post bears S 74° E 13.4 ft dist. for Sec. 14

A steel fence post bears N 74° W 22.9 ft dist. for Sec. 15

Attached warning and bearing tree signs to both posts.

A fire hydrant bears S 89° E 129.9 ft dist.

A fire hydrant bears S 23° E 47.4 ft dist.

STEEL POST CERTIFICATION I, George Clark certify the information shown herein is true and correct Signature of Ground Party Chief I, Ken Davis RLS certify that this confective represents work performed by Mr. Post Company of the Company of
STEEL POST Signature of Ground Party Chief I, Ken Dayle RLS certify this this poor correctly represents work performed by
STEEL POST Signature of Ground Party Chief I, Ken Dayle RLS certify this this poor correctly represents work performed by
STEEL POST I, Ken Davie RLS certification of the Contraction of the Co
STEEL POST I, Ken Davie RLS certification of the Contraction of the Co
STEEL POST Certificated blessor the record correctly represents work performed by Me or under my direction in compliance with the "Corner Recordation of the recorda
Me or under my direction in compliance with the "Corner Recordation 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
(1002-101 or see Micha)
N ENNET DE MONTO
The second secon
B Signature of Surveyor & Seal of 4975-5
ofice Hydrant Hydrant
Hydran
Sketch of Corner
Office of Clerk and Recorder, County of function.
The birth and Recorder, County or And the
This "corner record" was filed for record on 11/16/01
was noted on the cross-index plat and is assigned page No. 10542
was noted on the cross-index plat and is assigned page No
County Official

• THIS CORNER