INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6, Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION P.M.M. ____ Corner W1/16 Section 8 T. <u>30N</u> R. <u>31W</u> Lincoln County **ORIGINAL** Kootenai Engineering - 1986 Set a 5/8" diameter x 30" long rebar with plastic cap stamped M.D.L. 4232S. No bearing trees were available within limits. **FOUND** Found 5/8" rebar with plastic cap stamped as shown below. Corner was flush with ground. **ESTABLISH** Establish one new accessory for this corner A 12" Ponderosa Pine bears S9°E, 24.4 feet distant, blaze and scribe "1/16 S8 BT" Painted blaze red and attached bearing tree sign. Set a steel post 2.0 feet south and a steel post 2.0 feet east of corner monument. No trees within limits in Section 5. MDL 4232S CERTIFICATION TAPLES AMES Certify the information shown herein is true and correct. Signature Ground Party Chief gmes K certify that this Corner Record correctly me or under my direction in compliance Act" (70-22-101, et seq., M.C.A.) JAMES R. **12" PINE** STAPLES 9958 LS SKETCH OF CORNER Office of Clerk and Recorder, County of . This "corner 206759 BOOK: CCR CCGR'S PAGE: 11129 Pages: 1 record" was filed for record on ___ STATE OF MONTANA LINCOLN COUNTY was noted on the cross-index plat RECORDED: 10/16/2007 9:10 KOI: CCGR'S TAMMY D. LAUER CLERK AND BECORDER Ø. FEE: \$0.00 BY Tourse Carsel

TO: J.R.S. SURVEYING P.O. BOX 1050, LIBBY, MONTANA 59923 book no. County Official