I. <u>Record:</u> None	
II. <u>Found:</u> No record monuments found.	
III. <u>Perpetuation:</u> At the corner point, determined by s steel rebar 30 ins. long, 29 ins. in the g Aluminum cap marked as shown below fr	ground, with a 3 1/4 ins. diam.
A Western Larch, 12 ins. diam., bears S8°W, 26	6.30 ft. dist., scribed CESE 1/64 S8 BT.
A Western Larch, 10 ins. diam., bears S85°W, 40.90 ft. dist., scribed CESE 1/64S8 BT.	
Painted faces and 6 in. wide red bands to all Bearing Tree signs.	bearing trees and attached
Magnetic declination: 18° East	
Equipment used: Hand compass and loggers to	ppe
NOTE: Refer to "White Pines" Subdivision Plat Lincoln Co survey information.	T30N R31W CESE1/64SB 7322 LS 2012  county Records for additional
Kootenai Surveyors Inc., 314 California Av., Libby, MT.	
10"larch  S85*W  40.90 ft.  12" larch  SKETCH OF CORNER	CERTIFICATION  Kelly Rooney  certify the infermation shown herein is true and correctly for any correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)  Signature of Surveyor & Seal  Date: 04/9/2013 Reg. No. 7322LS  Employer: Kootenai Surveyors Inc.
Office of Clerk and Recorder, County of Lincoln	
·	Sec. 8  12030 Pages: 1  S  BBY, MT 59923

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

· corner this sheet

CERTIFIED CORNER RECORDATION

CE-SE 1/64 S8 T 30 N. R. 31 W. P.M.M. Lincoln County