

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

This corner is a Brass Cap set in a pile of rock by the Bureau of Land Management with two bearing trees.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: May 17th.

.1/4 Cor.

_____ 19.67, was noted on the cross-index plat and is

L. Vaughn County Official

30.

Eleanor

Cross Index No. R-19

1967

No work done as this corner set by Bureau of Land Management with two bearing trees and no one has disturbed either the corner or the wittness trees for the corner.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

Sec. 23, T. 30N., R.31 W.

22|23

| 27 26 | S. 89° 56' W 2618.12' | |
|-----------------|---|---------------------------------|
| Surveyor's Seal | • | DIAGRAM OF CORNER: |
| | certify that the information shown herein is true and correct. | พ. |
| •• | Signature of Ground Party Chief Donald D. Dahl | NV4 COE |
| | certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same. | |
| | Signature of Surveyor | == Corner recorded on the sheet |
| | 798-S. Registration Number | |

Office of Clerk and Recorder, County of Lincoln County. State of Montana.

This "corner record" was filed for record on the 5th day of October

<u>83</u>

FORM 125 - 41608