
CERTIFIED CORNER RECORDATION

Corner	C N 1/16	Sec.	33	Т.	30N	R.	31W	P.M., MT	Lincoln	County

I. 1973 B.L.M. subdivision survey by Hjellam and Pritchard: Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, in a collar of stone, with brass cap mkd. as shown.



Established two bearing trees:

A pine, 6 ins. diam., bears S9°W, 48 lks. dist., mkd. "CN 1/16 S33 BT". A pine, 6 ins. diam., bears N86 1/4°W, 127 lks. dist., mkd. "CN 1/16 S33 BT".

II. Found a 2 1/2 in. diam. iron pipe, 6 ins. above ground, firmly set, with a 3 1/4 in. brass cap mkd. as shown above, from which:


A pine, 11 ins. diam., bears S9°W, 31.7 ft. (48 lks.) dist., with visible scribing. A fallen pine snag, 8 ins. diam., bears N86°W, 83.8 ft. (127 lks.) dist., with visible scribing.

III. Established one new bearing tree:

A pine, 7 ins. diam., bears S80°W, 75.4 ft. dist., scribed "X BT".

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East



	neg. No.: 1322LS	616					
SKETCH OF CORNER	Employer: U.S. FOREST SERVICE						
on was noted on the cross-index plat and	was noted on the cross-index plat and is assigned page No. 9742						
	nty Official By DEB	• - corner this sheet					

Cross Index No. W-1

T. 30N

R. 31W F