
CERTIFIED CORNER RECORDATION

Corner	N 1/16	Sec.	8/9	Т.	30N	R.	31W	P.M., MT	Lincoln	County

I. 1974 B.L.M. Dependent Resurvey record by S. B. Hjellum and J. S. Pritchard: At the point for the N 1/16 section corner of sections 8 and 9 set an iron post, 28 ins., long, 2 1/2 ins. diam., 3 ins. below the surface of the ground, with a brass cap mkd:



from which:

A fir, 6 ins. diam., bears S60°E, 180 lks dist., mkd. "N 1/16 S9 BT". A twin larch, 8 ins. diam., bears S18 3/4°E, 130 lks. dist., mkd. "X BT".

The SW concrete foundation corner of a frame house, bears N60° 02' W, 78 lks. dist.

Found a rebar with a yellow plastic cap mkd. "JHN", 3 ins. below ground surface. (B.L.M. record indicates II.a brass cap was set).


from which

A fir, 11 ins. diam., bears S60°E, 118.8 ft. (180 lks.) dist., with healed face. A twin larch, 12 ins. diam., bears S19°E, 85.8 ft. (130 lks.) dist., with healed face.

The SW corner of house, bears N60°W, 51.5 ft. (78 lks.) dist.

III. Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East.



Sec. 8 LINCOLN. This "corner record" was filed for record Office of Clerk and Recorder, County of on JULY 29,1997 _ was noted on the cross-index plat and is assigned page No. CORAL M.CUMMINGS in book No. County Official - corner this sheet

F-09

30N