

**CERTIFIED LAND CORNER RECORDATION**

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

PART 1:

NORTHEAST Corner, NORTH  $\frac{1}{4}$  Corner, NORTHWEST Corner, SOUTHWEST Corner and SOUTH  $\frac{1}{4}$  Corner all brass caps found and replaced by U.S.B.L.M., in co-operation with U.S.F.S. WEST  $\frac{1}{4}$  Corner found 1  $\frac{1}{2}$ " pipe covered by previous recordation. EAST  $\frac{1}{4}$  Corner found mound of rock with corner tag by U.S.F.S. and old bearing tree. SOUTHEAST Corner not found.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED  
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: December, '71

PART 2:

Traversed from NORTHEAST Corner to all above given corners to establish all recorded corners.

(See back of this page)

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.  
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

(See back of this page)

DIAGRAM OF CORNER:

Surveyor's Seal

I, Michael R. Pine  
certify that the information shown herein is true and correct.


N. (see back of this page)

Michael R. Pine  
Signature of Ground Party Chief

I, Philip L. Sargent  
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

= Corner recorded on the sheet

Philip L. Sargent  
Signature of Surveyor



2235S  
Registration Number

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 10<sup>th</sup> day of January 1972, was noted on the cross-index plat and is assigned page No. 1, in book No. 253

ELEANOR L. VAUGHN by Vanda d. Higginson  
County Official Deputy

