

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner CE-SE 1/64 Section 29 T. 30 N. R. 33W. P.M.M. Lincoln County

I. 1986 Davis Surveying Inc.

I found a 5/8 inch dia. x 24 inch long rebar with an aluminum cap stamped:
 John J. Allen 3491 S. from which,
 A PINE, 10" DBH, bears Southwesterly 8.0 feet more or less.
 Painted a 6 inch wide red band around BT with BT sign on front and warning
 sign #54.9 on back.
 The original scribing not visible. I can still see blazed face on butt of
 tree.
 The corner is located up on hillside about 300 feet from flat.



SKETCH OF CORNER

CERTIFICATION

I, Kenneth E. Davis
 certify the information shown herein is true and correct.

Kenneth E. Davis
 Signature Ground Part, Chief
 KENNETH E. DAVIS
 I, Kenneth E. Davis
 certify that this Corner Record correctly represents work performed
 by me or under my direction in compliance with the "Corner
 Recordation Act" (70-22-701, et seq.)


Kenneth E. Davis
 Signature of Surveyor & Seal

Date: 9/86 Reg. No. 4975 S.
 Employer: Davis Surveying Inc.

Office of Clerk and Recorder, County of Lincoln. This "corner
 record" was filed for record on the Sept. 4 day of 1986
 was noted on the cross-index plat and is assigned page No. 3338, in
 book No. _____

Janet BF Sigel by Bill Buckhoff
 County Official Deputy

Sec. 29



Cross Index No. _____ T. _____ R. _____ P.M.M.

• - corner this sheet