equent record used to evaluate the corner position

2. Description of evidence found, note discrepancies in the record, state method

corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and scaled by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner N 1/16 Section 7 (only) T. 30 N R. 33 W P.M.M. Lincoln

Davis Surveying, Inc. 1987

I set a 5/8 inch dia. x 24 inch long rebar with yellow PVC cap stamped: K.E.D. 4975 S from which;

A 3 inch red fir bears N 22° W 29.10 feet from the center of the stree scribed "X". A 10 inch red fir bears N 1° W 31.5 feet from center of tree scribed N 1/16 S 7 BT notched at root crown.

Painted a 6 inch red band around BT's and placed location sign on front of trees.

The corner is located at the bottom of a rock ledge and has a pile of rock around it.

120.00 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CERTIFICATION 1. KEN E. DAVIS certify the information shown herein is true and correct. Signature Ground Party Chief
Rack Leone	certify that this Corner Record correctly represents work performed by me of under my disection in compliance with the "Corner Recordation Act" (70/22-101, et seq., M.C.A.) Signature of Surveyor & Scal Date: 9 87 Reg. No. 49755
SKETCH OF CORNER	Employer: Daws Dervey fre,
Office of Clerk and Recorder, County of Lincoh record" was filed for record on Lept 17, 1987	Sec. 7
was noted on the cross-index plat and is assigned page No	Sie Such
Cross Index No T Adopted July 1, 1981, Montana Board of Professional En	RPMM • - corner this sheet