CERTIFIED LAND CORNER RECORDATION

SECTION 20 TWP. 30 N., R. 33 W., M.P.M.

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Original W 1/4 Cor. - post with two B.T.s described in G.L.O. notes Steel "T" Bar set by #649 S
Original NW Cor. - post with marked stone and 2 B.T.s described in G.L.O. notes
replaced by # 649 S with steel "T" bar - 4 B.T.s

North $\frac{1}{4}$ Corner is a steel "T" bar with 2 B.T. s - set by others East $\frac{1}{4}$ Corner is a steel rod set by others South $\frac{1}{4}$ Corner is a steel rod set by others

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: July."74 & Jan. '75

Corners set by this survey are 2"x24" steel rods with caps stamped JN 534 E.S.

SEE DIAGRAM ON REVERSE SIDE

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)


SEE DIAGRAM ON REVERSE SIDE

Surveyor's Seal	Jack H. Ninneman	DIAGRAM OF CORNER:
	certify that the information shown herein is true and correct. Signature of Ground Party Chief Jack W. Ninneman	N. See reverse side
	certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same. Signature of Surveyor	= Corner recorded on the sheet
	#534 E.S. Registration Number	

Office of Clerk and Recorder, County of Ancula

This "corner record" was filed for record on the State day of State 19.5, was noted on the cross-index plat and is assigned page No. 389, in book No.

State State



Set ½"x24" Steel Rods
 With Caps Stamped J.N. 534 E.S.

At Remaining Subdivision Corner Designated
534 E.S. (No B.T.s Scribed or Posted)

MORTON - RANN-RANSAY