- Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.


 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

C-E-SE 1/64 Sec. 2 Lincoln P.M.M. Corner _ County No record found at Lincoln County Courthouse

II. No evidence on the ground

III. At the determined corner position by survey, set a 3/4 ins. dia. aluminum rod, 30 ins. long, 26 ins. in the ground with attached 3 1/4 ins. dia. U.S.D.A. Porest Service aluminum cap, marked as shown:



from which

A hemlock, 13 ins. dia., bears $\rm S12^{\circ}W$, 22.7 ft. dist., mkd. C-E-SE 1/64 S2 BT. A hemlock, 4 ins. dia., bears $\rm S73^{\circ}W$, 28.4 ft. dist., mkd. X BT.

Set a 6 ft. galvanized steel guard post with "Survey Marker" and "Property Boundary" decals attached, 3 ft. West.

Painted a red band around each bearing tree and attached "Land Survey Monument" and "Bearing Tree" signs.

Magnetic Declination: East, 20

4" HEMLOCK 13" HEMLOCK SKETCH OF CORNER

CERTIFICATIO	1(
--------------	----

Kenneth Kern

certify the information shown herein is true and correct.

certify that this Corner Record correctly represents

11/1<u>3/91</u> Reg. No. 7322

U.S. FOREST SERVICE

Office of Clerk and Recorder, County of	Lincolu	. This "corner
record" was filed for record on	1/ 22 22:	<i>i</i>
was noted on the cross-index plat and is	assigned page No	506d, in
book No.	County	official 5
		30 N . 34 W

Cross Index No. -

· corner this sheet