- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position.
- Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

C-N-SW-NW 1/256 Sec. 12 30 N., P.M.M. Corner. County No records found at Lincoln County Courthouse.

- No evidence on the ground.
- III. At the determined corner position by survey, set a 3/4 ins. dia. aluminum rod, 30 ins. long, 24 ins. in the ground with attached 3 1/4 ins. dia. U.S.D.A. Forest Service aluminum cap, marked as shown:



from which

A douglas fir, 11 ins. dia., bears N75 $^{\circ}$ E, 5.1 ft. dist., mkd. C-N-SW-NW 1/256 S12 BT. A douglas fir, 13 ins. dia., bears N89 $^{\circ}$ W, 20.4 ft. dist., mkd. C-N-SW-NW 1/256 S12 BT.

Painted a red band around each bearing tree and attached "Land Survey Monument" & "Bearing Tree" signs.

Magnetic Declination: East, 20°

CERTIFICATION Alvah F. Hughes certify that this Corner Record correctly repres <u>~8</u>9°W 11/13/91 Reg. No. 20 4 FT 7322 U.S. FOREST SERVÎCE Employer: **SKETCH OF CORNER**

Office of Clerk and Recorder, County of	Lincoln	This ''corner	Sec. 12	· · · · · · · · · · · · · · · · · · ·
record'' was filed for record on	4-22-92		-	
was noted on the cross-index plat and is	assigned page No.	5062 in		
book No.	County Of	<u> Esta margo</u> ficial	,	+ + -
	.25F21.5	30 N 34 W		لـــلــــــــــــــــــــــــــــــــــ

corner this sheet ___ R. _____ PMM Cross Index No. __ _ T. __