INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

NW 1/16 of Sec. 12 Lincoln P.M.M. _County Corner __ No records found at Lincoln County Courthouse.

II. No evidence on the ground.

III. At the determined corner position by survey, set a 3/4 ins. dia. aluminum rod, 30 ins. long, 26 ins. in the ground with attached 3 1/4 ins. dia. U.S.D.A. Forest Service aluminum cap, marked as shown:




from which

A spruce, 9 ins. dia., bears N4 $^{\circ}$ W, 40.5 ft. dist., mkd. NW 1/16 S12 BT. A douglas fir, 13 ins. dia., bears N80 $^{\circ}$ E, 2.5 ft. dist., mkd. NW 1/16 S12 BT.

Set a 6 ft. galvanized steel guard post with "Survey Marker" and "Property Boundary" decals attached, 3 ft., North.

Painted a red band around each bearing tree and attached "Land Survey Monument" & "Bearing Tree"

Magnetic Declination: East, 20



| SKETCH OF CORNER | | Employer: U.S. FOREST SERVICE? | |
|--------------------------------------|-------------------------|--------------------------------|--------------------------|
| Office of Clerk and Recorder, Count | y of Lincoln | This "corner | Sec. 12 |
| record" was filed for record on | 4-22-92 | | - |
| was noted on the cross-index plat an | id is assigned rage No. | 5069, in | +- +-+- |
| book No. | • | | |
| | F22 Cross Index No. | 30 N 34 W | MM ● - corner this sheet |

_____ T. _____ R. _____ PMM Cross Index No. -