INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated 2. Description of monument and accessories set to perpetuate the corner position.
- Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and scaled by Land Surveyor registered in the State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CENTILLE COMMEN MECOMBATIO	ED CORNER RE	CORDATION
----------------------------	--------------	-----------

Corr	NW 1/16 Sec. 1	30 N., TR	34 w., P.M.	Lincoln M.	County
	No record found at Lincoln County			•	,
11.	No evidence on the ground.				
	At the determined corner position				
	27 ins. in the ground with attache marked as shown:			aluminum cap.	
		NW 1/16 S 1 7322 LS 1992			

from which

A fir, 14 ins. dia., bears N42 $^{\circ}$ W, 64.1 ft. dist., mkd. NW 1/16 S 1 BT. A birch, 6 ins. dia., bears N2 $^{\circ}$ W, 14.9 ft. dist., mkd. NW 1/16 S 1 BT.

Set a 6 ft. galvanized steel guard post with "Survey Marker" and "Property Boundary" decals attached, West, 3ft.

Painted a red band around each bearing tree and attached "Land Survey Monument" and "Bearing Tree" signs.

Magnetic Declination: East, 20°

