INSTRUCTIONS


- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

C-S-SW-NE 1/256 Sec. 1 Lincoln P.M.M. Corner_ County

- No record found at Lincoln County Courthouse.
- No evidence on the ground.
- III. At the determined corner position by survey, set a 3/4 ins. dia. aluminum rod, 30 ins. long, 28 ins. in the ground, with attached 3 1/4 ins. dia. U.S.D.A. Forest Service aluminum cap marked as shown:



from which

A fir, 10 ins. dia., bears $866^{\circ}E$, 17.7 ft. dist., mkd. C-S-SW-NE 1/256 S 1 BT. A fir, 10 ins. dia., bears $844^{\circ}W$, 23.5 ft. dist., mkd. C-S-SW-NE 1/256 S 1 BT.

Set a 6 ft. galvanized steel guard post with "Land Survey Monument" and "Property Boundary" decals attached. North, 3 ft.

Painted a red band around each bearing tree and attached "Land Survey Monument" and "Bearing Tree" signs.

Magnetic Declination: East, 20

S 66° F 17.7 Pt. 10° Fil CERTIFICATION Kenneth R. Kern certify the information sho correct. 10%, Surewill 35.5CX certify that this Corner Record correctly represente w 6/10/92

SKETCH OF CORNER	Employer:	U.S. FOR	EST SERVIOR	TAND 3
Office of Clerk and Recorder, County of Julion	This ''co	orner	Sec. 1	
record" was filed for record on Cipul 8, 199	94			
was noted on the cross-index plat and is assigned page No.	237	_ , in		
book No County Office	ial S	DB.		
B .75-23.5	30 א 3	4 w		

• - corner this sheet Cross Index No. ___