INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner CS 1/16 cor. Sec. 33

No original corner set by GLO.

Set a 3" USFS Aluminum driveable monument 30" long, 21" deep w/ 34" alum. Corner falls on W. fill slope of old logging road approx. 25 feet W. of centerline. Corner falls 150'S. of SW'ly coulee. cap mkā: S1/16| S33 1987


3976ES

A fir 8" bears N8 E 21.7 feet, mkd. CS1/16 S33 BT. Bearing trees: A fir 7" bears N86°W 7.9 feet, mkd. CS1/16 S33 BT.

Built a rock cairn 3' diam around mon. and cleared to 6' diam. Set a sign post near corner. Painted and signed all bearing trees as per USFS Specs.

Decl. 20°E (assumed).

Cor. Mkd: 1987 3976ES



CERTIFICATION Dannist Pullindoutt the information shown herein is true and correct. Signature Ground Party Chief Robert E. Findorff /11/87 Reg. No. 3976E\$ Employer: Self

SKETCH OF	CORNER	(SEE	ABOVE)

Office of Clerk and Recorder, County of Lincoln. This "corner	Sec.33,1	231N,R30W
record" was filed for record on Nov 16, 1987		
was noted on the cross-index plat and is assigned page No. 3699, in	,	
book No Suit St Deep by Seel Suely	-+-	-
Country Official Explay		1 1

Y-11Cross Index No. .

_ T. 31N R. 30W PMM

· - corner this sheet