

CERTIFIED LAND CORNER RECORDATION

(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found a standard brass cap monument marked as shown.

From which: A 10" doug. fir bears S8°E, 27.3 ft., scribed CS 1/16 S32 BT
An 8" doug. fir bears N47°E, 13.1 ft., scribed CS 1/16 S32 BT



DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


Date of work: 1979

Set a $2\frac{1}{2}$ " x 30" aluminum pipe, 2μ " in ground, raise a mound of stone around pipe. Al. cap stamped as shown: from which;

A douglas fir, 10" dia., bears S2°W, 28.8 Ft. scribed CS 1/16 S32 BT

A douglas fir, 8" dia., bears N54°E, 14.7 Ft., scribed CS 1/16 S32 BT

Place N. F. Boundary post at corner position.



SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

The discrepancy noted in the corner position is the result of the method used in section subdivision.

See Certificate of Survey No. 753

N68°43'22"E 2.23'

Surveyor's Seal




I, Anthony J. Bachman
certify that the information shown herein is true and correct.

Kony J. Backman
Signafure of Ground Party Chief

Signature of Surveyor

DIAGRAM OF CORNER:



= Corner recorded on the sheet

5612-S Registration Number

9.	
Office of Clerk and Recorder, County of Lincoln)
This "corner record" was filed for record on the 314. day of .	March 1980, was noted on the cross-index plat and is alleanor de Vaugha, day betty besty County Official
assigned page No. 635 in book No.	bleanor of Vanda les best best, -
	County Official Diputy
	Cross Index No. 17 T 3/ R 30 Mer.