
CERTIFIED CORNER RECORDATION

Corner	MS 10964 COR. 3	Sec.	26	T.	31N	R.	30W	P.M., MT.	Lincoln	County
	EASTSIDE NO. 1									

1976 Original B. L. M. survey by Arthur C. Rader: Cor. No. 3, identical to Cor. No. 2 of the Eastside No. 2 Lode of this I. survey. Set an iron post,1 in. diam., 30 ins. long, 24 ins. in the ground, with brass cap mkd. 3-ES1 2-ES2-10964; from which:

> A larch, 12 ins. diam., bears NORTH, 16.4 ft. dist. mkd. 3-ES1-10964 BT. A pine, 10 ins. diam., bears N 7°00' W, 0.2 ft. dist., mkd. 2-ES2-10964 BT.

Found a 1 1/2 in. diam. iron pipe, 10 ins. above ground, firmly set, with a 3 in. diam. brass cap, mkd. as shown:. П.



from which:

A larch, 14 ins. diam., bears NORTH, 16.4 ft. dist., mkd. with visible scribe marks.

A dead and down pine, 10 ins. diam., bears N 7°W, 0.2 ft. dist., mkd. with visible scribe marks. A steel guard post with Property Boundary decal attached, bears SOUTH, 1.2 ft. dist.


A steel guard post with Property Boundary decal attached, bears WEST, 1.3 ft. dist.

III. Establish one new bearing tree:

A larch, 10 ins. diam., bears S 2°E, 24.6 ft. dist., mkd. X BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East.



Office of Clerk and Recorder, County of This "corner record" was filed for record cross-index plat and is assigned page No 8202 was noted on in book No. __ County Official



- corner this sheet

Cross Index No

Cor. 3 M.S. 10964 Eastside Lode No. 1

31N

30W