CERTIFIED CORNER RECORDATION

Corner	MS 10964 COR. 3	Sec.	26	T.	31N	R.	30W	P.M., MT.	Lincoln	County
	EASTSIDE NO. 9									

I. 1976 Original B. L. M. survey by Arthur C. Rader: Cor. No. 3. Set an iron post, 1 in. diam., 30 ins. long, 24 ins. in the ground, with brass cap mkd. 3-ES9-10964; from which:

A larch, 24 ins. diam., bears N 3° 06' E, 14.0 ft. dist. mkd. 3-ES9-10964 BT. A fir, 12 ins. diam., bears N 75° 55' W, 24.6 ft. dist., mkd. 3-ES9-10964 BT. A cor. of the location bears S 37° 19'W, 28.3 ft. dist.

II. Found a 1 1/2 in. diam. iron pipe, 14 ins. above ground, firmly set, with a 3 in. diam. brass cap, mkd. as shown:



from which:

A larch, 18 ins. diam., bears N 3°E, 14.0 ft. dist., mkd. with visible scribe marks.

A dead spruce, 11 ins. diam., bears N 76°W, 24.6 ft. dist., mkd. with visible scribe marks. (Rec: fir.)

A steel guard post bears NE, 1.7 ft. dist., with a property boundary decal attached.


A steel guard post bears NW, 4.9 ft. dist., with a property boundary decal attached.

III. Established one new bearing tree:

A spruce, 10 ins. diam., bears S 16°E, 6.6 ft. dist., mkd. "X" BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East.



SKETCH OF CORNER

Emptoyer _U.S. FOREST SERVICE

Sec. 26

Office of Clerk and Recorder, County of ______. This "corner record" was filed for record on _______. was noted on the cross-index plat and is assigned page No.82/6, in book No. _______. County Official

Cross Index No Cor. 3 M.S. 10964 Eastside No. 9 T. 31N R. 30W PMM