
CERTIFIED CORNER RECORDATION

Sec. T. 30W P.M., MT. MS 10965 COR. 1 14 31N R. Lincoln Corner County CPD NO. 34 LODE

1976 Original B. L. M. survey by Arthur C. Rader: Cor. No. 1, identical with Cor. No. 2 of the CPD No. 39 lode, of this I. survey. Set an iron post, 30 ins. long, 1 in. diam., 24 ins. in the ground, with brass cap mkd. 1CPD34 2CPD39-10965; from which:

> A larch, 12 ins. diam., bears N 12°40' E, 9.4 ft. dist. mkd. 1CPD34-10965 BT. A pine, 10 ins. diam., bears S 62°30' W, 5.0 ft. dist., mkd. 2CPD39-10965 BT. A cor. of the location bears N 42°54' E, 1.0 ft. dist.

Found a 1 1/2 in. diam. iron pipe, 17 ins. above ground, firmly set in a collar of stone, with a 3 in. diam. brass cap, mkd. as II. shown:



from which:

A dead and down pine, 11 ins. diam., bears S 84°W, 5.0 ft. dist., mkd. 2CPD39-10965 BT. (Rec: S 62° 30'W) A larch, 12 ins. diam., bears N 24°E, 9.5 ft. dist., mkd. 1CPD34-10965 BT. (Rec: N 12° 40'E)

III. Established one new bearing tree:


A larch, 7 ins. diam., bears S 60°E, 25.9 ft. dist., mkd. 1 CPD34 10965 BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Set a steel guard post with Property Boundary decal attached, SE of the corner, 1.0 ft. dist.

Magnetic Declination: 20° East.





CERTIFICATION
i. Jeff Hintz
certify the information shown herein is true and correct.
certify the information shown herein is true and correct.
Signature Ground Party Chief
. Ronald A. Pearson
certify that this Corner Record correctly represents work performed by me or
under my direction in compliance with the "Corner Recordation Act" (70-22-
101, et seq., M-C.A.)
Signature of Surveyor & Seal
· · · ·
Date: 1/22/96
Reg. No.: 9008LS
Employer _U.S. FOREST SERVICE

	Sec. 1
Office of Clerk and Recorder, County of Julean. This "corner record" was filed for record	
on $3-28-96$ was noted on the cross-index plat and is assigned page No. 8229 ,	}
in book No (vial M. Cumming B. B.	}
County Official	• - corn