

CERTIFIED CORNER RECORDATION

Corner MS 10935 WC COR. Sec. 10 T. 31N R. 30W P.M., MT. Lincoln County
2 RAINY NO. 14

- I. 1972 Original B. L. M. survey by Arthur C. Rader: True point for Cor. No 2 falls on shoulder of road. Thence N 89°54'E, 9.5 ft. dist. to the witness corner to Cor. No. 2. Set an iron post, 1 1/2 ins. diam., 30 ins. long, 24 ins. in the ground, with brass cap mkd. WC 2-R14-10935. No bearing trees available.
- II. Found a 1 1/2 in. diam. iron pipe, 14 ins. above ground, firmly set, with a 3 1/4 in. diam. brass cap, mkd. as shown:.



from which:


A 6 ft. steel guard post bears N 89°E, with Property Boundary decal attached.

- III. Establish two new bearing trees:

A fir, 6 ins. diam., bears N 56°E, 23.3 ft. dist., mkd. X BT.
A pine, 6 ins. diam., bears N 58°W, 23.6 ft. dist., mkd. X BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East.



SKETCH OF CORNER

CERTIFICATION

I, Thomas M. Hommel
certify the information shown herein is true and correct.

Thomas M. Hommel
Signature Ground Party Chief

I, Ronald A. Pearson
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

Ronald A. Pearson
Signature of Surveyor & Seal

Date: 1/23/96

Reg. No.: 9008LS

Employer U.S. FOREST SERVICE

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on 2-28-96 was noted on the cross-index plat and is assigned page No. 8231, in book No. _____

Coral M. Cumming G.P.S.
County Official

