
## CERTIFIED CORNER RECORDATION

Corner	MS 10935 COR. 3	Sec.	10	Т.	31N	R.	30W	P.M., MT.	Lincoln	County
	RAINY NO. 12									

- 1972 Original B. L. M. survey by Arthur C. Rader: Cor. No. 3. Set an iron post, 1 1/2 ins. diam., 30 ins. long, 24 ins. in the I. ground, with brass cap mkd. 3-R12-10935. No bearing trees available.
- Found a 1 1/2 in. diam. iron pipe, 11 ins. above ground, firmly set, with a 3 1/4 in. diam. brass cap, mkd. as shown: II.



from which:

A 6 ft. steel guard post bears NORTH, 3.3 ft. dist., with a Property Boundary decal attached. A 6 ft. steel guard post bears N 52°E, 2.4 ft. dist., with a Property Boundary decal attached.

IΠ. Establish two new bearing trees:

> A fir, 9 ins. diam., bears N 37°E, 34.2 ft. dist., mkd. 3 R 12 10935 BT. A pine, 6 ins. diam., bears N 61°W, 17.1 ft. dist., mkd. X BT.


Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East.



CERTIFICATION Jeff Hintz the information shown herein is true and correct. Signature Ground Party Chief Ronald A. Pearson 0 1/23/96 Reg. No.: 9008LS Employer <u>U.S. FOREST SERVICE</u> **SKETCH OF CORNER** 

Office of Clerk and Recorder, County of This "corner record" was filed for record on <u>2-28-96</u> was noted on the cross-index plat and is assigned page No. 8232, in book No. \_\_\_ County Official



T.

PMM