


CERTIFIED CORNER RECORDATION

Corner MS 10965 COR. 2 Sec. 23 T. 31N R. 30W P.M., MT. Lincoln County
CPD NO. 11 LODE

I. 1976 Original B. L. M. survey by Arthur C. Rader: Cor. No. 2. Set an iron post, 30 ins. long, 1 in. diam., 24 ins. in the ground, with brass cap mkd. 2CPD11-10965; from which:

- A larch, 12 ins. diam., bears S 10° W, 23.0 ft. dist. mkd. 2CPD11-10965 BT.
- A larch, 10 ins. diam., bears S 85°40' W, 14.3 ft. dist., mkd. 2CPD11-10965 BT.
- A cor. of the location bears East, 1.0 ft. dist.

II. Found a 1 1/2 in. diam. iron pipe, 13 ins. above ground, firmly set in a collar of stone, with a 3 in. diam. brass cap, mkd. as shown:.





from which:

- A larch, 11 ins. diam., bears S 35°W, 23.0 ft. dist., mkd. with visible scribe marks. (Rec: S 10°W)
- A larch, 8 ins. diam., bears N 75°W, 14.3 ft. dist., mkd. with visible scribe marks. (Rec: S 85° 40' W)
- A steel guard post bears NORTH, 1.6 ft. dist., with Property Boundary decal attached.
- A steel guard post bears WEST, 0.8 ft. dist., with Property Boundary decal attached.

III. Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East.



SKETCH OF CORNER

CERTIFICATION

I. Jeff Hintz
 certify the information shown herein is true and correct.

Signature Ground Party Chief

I. Ronald A. Pearson
 certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

Signature of Surveyor & Seal

Date: 1/22/96

Reg. No.: 9008LS

Employer U.S. FOREST SERVICE

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on 2-28-96 was noted on the cross-index plat and is assigned page No. 8234, in book No. _____

Coral M. Cummings By OB
 County Official

Sec. 23

● - corner this sheet