
CERTIFIED CORNER RECORDATION

Corner MS 10965 COR. 1 Sec. 14 T. 31N R. 30W P.M., MT. Lincoln County CPD NO. 11 LODE

I. 1976 Original B. L. M. survey by Arthur C. Rader: At Cor. No. 1 of the CPD No.11 lode, identical with Cor. No. 2 of the CPD No. 16 lode, and Cor. No. 3 of the CPD No. 17 lode, both of this survey. Set an iron post, 30 ins. long, 1 in. diam., 24 ins. in the ground, with brass cap mkd. 1CPD11 2CPD16 3CPD17-10965; from which:

A pine, 12 ins. diam., bears S 18°35' E, 5.0 ft. dist. mkd. 1CPD11-10965 BT. A pine, 12 ins. diam., bears N 35°05' W, 15.8 ft. dist., mkd. 3CPD17-10965 BT. A cor. of the location bears East, 1.0 ft. dist.

II. Found a 1 1/2 in. diam. iron pipe, 14 ins. above ground, firmly set in a collar of stone, with a 3 in. diam. brass cap, mkd. as shown:.



from which:

A pine stump, 14 ins. diam., bears S 18°E, 5.0 ft. dist., with no visible scribe marks.

A steel guard post bears SE, 1.3 ft. dist., with Property Boundary decal attached.


A steel guard post bears NE , 1.0 ft. dist., with Property Boundary decal attached.

III. Established two new bearing trees:

A larch, 15 ins. diam., bears N 86°E, 34. 2 ft. dist., mkd. 1CPD11-10965 BT. A fir, 17 ins. diam., bears N 32°W, 41.1 ft. dist., mkd. X BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East.



SKETCH OF CORNER

Signature Ground Parity Chief

I. Ronald A. Pearson

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the Corner Recordation Act (70-22-101) et seq., M.C.A.)

Signature of Surveyor & Seal

Date: 1/22/96

Reg. No.: 9008LS

Employer U.S. FOREST SERVICE

Office of Clerk and Recorder, County of Juncol. This "corner record" was filed for record on ________ was noted on the cross-index plat and is assigned page No. <u>B235</u>, in book No. ________ was noted on the cross-index plat and is assigned page No. <u>B235</u>,

