	CERTIFIED CORNER RE	CORDATION	
Corne	r <u>CN 1/16 S30</u> T <u>31 N.</u> R. <u>31</u>	W. P.M.M	Lincoln County
I.	Record: 2000 Certificate Survey No. 2963 Lincoln	County Records, b	by Smith Surveying.
II.	Found: A 5/8 inch diam. rebar with plastic cap N28°54'56"E, 3.66 ft. dist. from the accepted this survey.		
III.	Perpetuation: At the corner point, determined by steel rebar 30 ins. long, 27 ins. in the Aluminum cap marked as shown below	ground, with a 3	
	A larch, 10 ins. diam., bears S51° E, 54.05 t	t. dist., scribed CN	1/16 S30 BT.
	A larch, 13 ins. diam., bears N41°W, 38.65 ft. dist., scribed CE 1/16 S30 BT.		
Painted faces and 6 in. wide red bands to all bearing trees and attached Land Survey Monument and Bearing Tree signs.			
Set a steel fence post along side set monument.			
	Magnetic declination: 18° East		
Equipment used: Hand compass and loggers tape			
	_ q. q		
		T31N R3 C N1/16 S3 C 7322 I 2010	30 LS
NOBLE Sec	otenai Surveyors Inc., 314 California Av., Libby, MT. 30 13" Larch 10" Larch SKETCH OF CORNER	certify the information a Signature Alvah F. Huston and the former Recordation Signature of Signature of Date: 01/14/2010 Re	ATTRICATION HUGHES 7322 LS coney chown herein is true and correctly from the second corpectly represents work there my direction in compliance with Act 70-22-101, et seq., M.C.A.)
Office of	of Clerk and Recorder, County of Lincoln This	"corner	
	ted on the cross-ind STATE OF MONTANA LINCOLN COUNTY	LIBBY, MT 59923	Sec. 30

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

· corner this sheet