	CERTIFIED CORNER RE	CORDATION
Corner	NW 1/16 S1 T. 31 N. R. 31	W. P.M.M. Lincoln County
I.	Record: None	
п.	Found: No record monuments found.	
III.	Perpetuation: At the corner point, determined by steel rebar 30 ins. long, 29 ins. in the Aluminum cap marked as shown below	ground, with a 3 1/4 ins. diam.
	A Douglas fir 12 ins. diam., bears S36'W, 15.	60 ft. dist., scribed NW 1/16 S1 BT.
	A Douglas fir, 14 ins. diam., bears N85*W, 33	3.60 ft. dist., scribed NW 1/16 S1 BT.
	Painted faces and 6 in. wide red bands to a Survey Monument and Bearing Tree signs.	ll bearing trees and attached Land
	Magnetic declination: 18° East	
	Equipment used: Hand compass and loggers	tape
		T31N R31W NW1/16 S1 7322 LS 2013
	E:Refer to Certificate of Survey NoLincolr survey information.	
	tenai Surveyors Inc., 314 California Av., Libby, MT.	. 59923 (406) 293-4354 CERTIFICATION
Sichting -Se	14" fir N85 W 33.60 ft.	Signature Ground Party Chief Alvah F. Hughes certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et.) HUGHE Signature of Surveyor & Seal 73 2 2 L 5 Date: 04/1/2013 Reg. No. 7322LS. 6 5 11
	SKETCH OF CORNER	
record" v	ed on the cros: STATE OF MONTANA LINCOLN COUNTY RECORDED: 05/06/2013 1:50 KOI: CC&R'S	Sec. 1 2025 Pages: 1 Account deputy , MT 59923

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

· corner this sheet