

#509


INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner S 1/16 Section 9-10 T. 31N R. 31W P.M.M. Lincoln County

- 1) No Original Record
- 2) N/A
- 3) I set a 5/8" x 24" Rebar, capped MDL 4232-S from which a Douglas Fir, 6" dia., bears N36°W 31.4 feet and a Douglas Fir, 1.5" dia., bears N45°E 48.4 feet, both scribed and tagged.



1-1/4" PVC Cap on 5/8" x 24" Rebar.

SKETCH OF CORNER

CERTIFICATION

I, L. A. Dolezal

certify the information shown herein is true and correct.

L. A. Dolezal
Signature Ground Party Chief

I, Melvin D. Lauteren

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-104, M.C.A.)


Melvin D. Lauteren
Signature of Surveyor & Seal

Date: 9-3-81 Reg. No. 4232-S

Employer: Kootenai Engineering, Inc.

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the 11th day of Sept 1981, was noted on the cross-index plat and is assigned page No. 1228, in book No. 1 Wesley S. Thompson, by Betty
County Official Deputy

Cross Index No. H-13 T. 31 R. 31 P.M.M.



• - corner this sheet

