CERTIFIED LAND CORNER RECORDATION

Section 25 Township 31 North, Range 31 West M.P.B. and M.

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

South 1/4 corner and closing corner Sections 30 and 31 found 2" Brasscaps by Corps of Engineers.

Section corner 25, 31 and 36 found 1-1/2" Brass Caps

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: April, 1975

East 1/16 corner to sections 25 and 36 set 1/2" I.D. pipe with Plastic Plug marked (W and R) in large field with no trees available.

(4232S)

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Reverse Side

	Molaria D. Lautaman	DIAGRAM OF CORNER:
Surveyor's Seal	I, Melvin D. Lauteren certify that the information shown herein is true and correct. Signature of Ground Party Chief	N. See Reverse Side
	I, Melvin D. Lauteren certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same. Signature of Surveyor	= Corner recorded on the sheet
	4232S Registration Number	
Office of Clerk and Recorder, Co	ounty of Lincoln	
This "corner record" was filed assigned page No	for record on the 30 day of April 1975, was	s noted on the cross-index plat and is

Form 125-3437

Cross Index No. 1 24 T. 3/ R. 3/

N 89-47-39 W 25-99,56 2 INCH BRASS CAP CARPS OF ENGINEERS.
SET 1/2 INCH I.D. DIPE W/CAP MARKED "WIR 42325
I'Z INCH BRASS CAP O I'S INCH BRAZE