DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

At the C-N-S-SE 1/256 Cor. of Section 2, T31N, R31W, Lincoln County, Montana;

No Original Record.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

10-18-79

Date of work:..

N-S-SE

1/25 4

3153*E*5

Set a 2" x 30" pipe, 26" in the ground, with mound of stone. Cap marked as illustrated for exact corner position, FROM WHICH: $\sqrt{s_z}$

A 6" fir bears N.77°E., 66.11 feet A 6" pine bears S.04°E., 66.3 feet

Note: Corner falls in South track of old skid road.

Variance Used: 17-1/2°

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey No. _______.

Surveyor's Seal

I, Paul S. Long
certify that the information shown herein is true and correct.

Signature of Ground Party Chief

THOMAS M. HANSON
I, THOMAS M. HANSON

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

THOMAS M.

Signature of Surveyor: 3153FS

DIAGRAM OF CORNER:

731A R31W

SEC+10A Z

N.

SEC. #Z

Corner recorded on the sheet

Office of Clerk and Recorder, County of INCO.

This "corner record" was filed for record on the // day of DlC 19.79, was noted on the cross-index plat and is assigned page No. 58.7 , in book No. 1 County Official Cross Index No.DE-20 T 31N R 31W Mer.