## CERTIFIED LAND CORNER RECORDATION

(REFERENCE FSM 7153.53)

## DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found a  $2\frac{1}{2}$ " X 30 iron pipe 26" in the ground, with brass cap marked. From which, A pine 17" dia., bears  $S6\frac{1}{2}^{0}$ W, 10 lks. dist., marked  $\frac{1}{4}$ S BT.

A pine 21" dia., bears N85 $^{14}_{4}$ OW, 14 lks. dist., marked  $^{14}$ S BT with an overgrown blaze.

T31N R31W/

14 <u>S24'</u>
S255

1962
BLM

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 1978

Corner is in good shape as found. BT's have healed blazes. I hang ribbon in area and on BT's to perpetuate corner.

Refer to Certificate of Survey, subdivision of section 24 T31N R31W, as recorded in Lincoln County Courthouse, Libby, Montana.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

STANLEY J.
SHEUSEN
2532 S

2532 S

SURVEYOR

Surveyor's Seal

I, Stephen D Staab CR. L.S. 1672

certify that the information shown herein is true and correct.

Signature of Ground Party Chief

Stanley J. Skousen 2532-S

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

tarley - Skousen
Stranger of Surveyor

DIAGRAM OF CORNER:

N. T31N R31W S24

= Corner recorded on the sheet

25325
Registration Number

Office of Clerk and Recorder, County of LINCOLN	
This "corner record" was filed for record on the 17th day of	Desember 1979., was noted on the cross-index plat and is
assigned page No, in book No	Desember 1979, was noted on the cross-index plat and is  County Official  Cross Index No. P 2 3 T 3/N P 3/W Mer
	Cross Index No. P 2 3 T 3/N B 3/W Mer