CERTIFIED LAND CORNER RECORDATION

(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

No original record of corner establishment on file. No evidence of corner found on ground.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 1978...

T31N R31W C E SW: NW:

> 1/256 **S24**

> > 2532-S 1978


Set a $2\frac{1}{2}$ " x 30" aluminum pipe with cap, 24" in the ground. Raised a rock mound around cap, from which a:

Fir 10" dia. bears N880W 18.7 feet marked CESWNW 1/256 S24 BT.


Fir 8" dia. bears N85⁰E 20.2 feet marked CESWNW 1/256 S24 BT

Refer to Certificate of Survey, subdivision of Section 24, T31N, R31W, as recorded in Lincoln County Courthouse, Libby, Montana.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



Surveyor's Seal



Stephen D. Staab OR. L.S. 1672

certify that the information shown herein is true and correct


> Signature of Ground Party Chief Stanley J. Skousen 2532-S

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

25325 Registration Number DIAGRAM OF CORNER:

N. T31N R31W S24 C-E-SW-NW 1/256



Corner recorded on the sheet

Office of Clerk and Recorder, County of LINCOLN	
	December 1979, was noted on the cross-index plat and is
assigned page No, in book No	County Official Letty Dael
	Cross Index No. 022 T. 31N R. 31W Mer.