CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

No original record other than this corner (a hub & tack) has been used for control on many surveys, and has been accepted as occupying the position of the N 1/16 corner of Sections 35 & 36, T31N, R31W, P.M.M.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: July, 1979

I set a 5/8 inch rebar tagged MDL 4232-S and made 2 (two) bearing trees as shown on reverse.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

SEE REVERSE:

Surveyor's Seal




I, Full Full Formation shown herein is true and correct.

Signature of Ground Party Chief

I, Certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

4232-S Registration Number DIAGRAM OF CORNER:



Corner recorded on the sheetN 1/16 COR.

N 116 COR. SECTIONS 35 & 36 T31N, R31W,

P.M.M.

Office of Clerk and Recorder, County of Amialn

This "corner record" was filed for record on the 30 day of April 1980, was noted on the cross-index plat and is assigned page No. 772, in book No.

Sellanar A. Daughn, by Detty Dell, County Official

3 Form 125-7887

Ď. the foote on si . bearing · , M'ONUMENT 8"P. PINE 4" x 4" CONCRETE 1/16 CORNER 589°20′50″ 224.60′