

CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Section 33 Twp. 31 N., R. 31 W., M.P.M. --- Northwest corner, southwest corner, east $\frac{1}{4}$ corner, and southeast corner are all standard brass capped monuments. The west $\frac{1}{4}$ corner is a pipe in fence line. The south $\frac{1}{4}$ corner has been destroyed.
There is a steel rod at the southeast corner of the SW $\frac{1}{4}$ SW $\frac{1}{4}$ SW $\frac{1}{4}$ said Section.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

We set a steel rod 25.0 feet east of the northwest corner of the SW $\frac{1}{4}$ SW $\frac{1}{4}$ of said Section 33 and a steel rod at the northeast corner of the NW $\frac{1}{4}$ SW $\frac{1}{4}$ SW $\frac{1}{4}$ of said Section.
No bearing trees in limits.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See other side.

Surveyor's Seal


I, J.W. Ninneman
certify that the information shown herein is true and correct.

J.W. Ninneman
Signature of Ground Party Chief

I, J.W. Ninneman
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

J.W. Ninneman
Signature of Surveyor

DIAGRAM OF CORNER:



534 E.S.
Registration Number

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 8th. day of September 19 67, was noted on the cross-index plat and is assigned page No. 78, in book No. 1

ELEANOR L. VAUGHN, By: Verda Bligh
County Official Deputy.

#78

STATE OF MONTANA
COUNTY OF LINCOLN

Filed this 8th day of
September A.D. 1967
at 11:05 M.
Eleanor J. Thompson
County Clerk
By Gary Watson Deputy

