
CERTIFIED CORNER RECORDATION

Corner CN 1/16 Sec. 35 T. 31N R. 31W P.M., MT Lincoln County


I. 1977 Certificate of survey No. 354 ByM.D.L. No. 4232S: Set by survey, a 2 1/2 in. diam. iron pipe, with a 2 3/4 in. diam., brass cap mkd. as shown:



II. Found a 2 1/2" iron pipe, protruding 12 ins. above a collar of stone, firmly set, with a 2 3/4 in. diam. brass cap mkd as shown above. from which:

A fir, 11 ins. diam., bears S53°E, 1.3 ft. dist., mkd. with a healed face. A fir, 20 ins. diam., bears N23°W, 20.5 ft. dist., with a pitched face.


III. *Amended the monument as shown below:






Set a 6 ft. steel guard post, West, 12.0 ft., with Land Survey Monument and Property Boundary decals. Set a 6 ft. steel guard post, North, 20.0 ft., with Land Survey Monument and Property Boundary decals. Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East.





Cross Index No

W-19

^{т.} 31N

W P.M., MT