
CERTIFIED CORNER RECORDATION

Corner C-S-S-S 1/256 Sec. 25 T. 31N R. 31W P.M., MT Lincoln County

I. 1987 Corner Recordation by Ken E. Davis #4975-S: "I found a MDL rebar and cap which I replaced with a 3 /14 in. diam. USDA Forest Service Monument.. Set a U.S.D.A. alum. cap and pipe, 3 1/4 ins. diam. X 30 in. long, mkd. as shown."



from which:

A fir, 4 ins. diam., bears N50°E, 13.0 ft. dist., mkd. "X BT". A pine, 10 ins. diam., bears S22°W, 28.5 ft. dist., mkd. "C-S-S-S 1/256".

Set a alum. post, 1.0 ft. NW of monument.

II. Found a 3/4 in. diam. alum. rod, 3 ins. above ground, firmly set, with a 3 1/4 in. alum. cap mkd. as shown above, from which:


A fir, 4 ins. diam., bears N50°E, 13.0 ft. dist., "BT" is visible. A fallen pine, 10 ins. diam., bears S22°W, 28.5 ft. distant.

III. Established one new bearing tree:


A fir, 7 ins. diam., bears N41°W, 18.5 ft. dist., scribed "CSSS 1/256 S25 BT".

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East



Office of Clerk and Recorder, County of ________. This "corner record" was filed for record on _________ was noted on the cross-index plat and is assigned page No. 9726, in book No. ________ CORAL M.CUMMINGS County Official



Cross Index No. U.75-23

· 31N ^{R.} 31W ^{PM}